## 2015 Porsche Boxster GTS Service History (CPO Warranty Until 04/21/2021)

| Mileage                                    | Date     | Service Performed   | Provider   | Location   | Cost                  | Maintenance | Upgrades            | Post-Warranty Repairs  |
|--|----------|---|--|--|-----------------------|-------------|---------------------|------------------------|
| 0  | 06/23/14 | Production  | Porsche Cars North America   |  |                       |             |                     |                        |
| 28   | 08/22/14 | Pre-Delivery Inspection   | Fletcher Jones Porsche of Fremont  | Fremont, CA  |                       |             |                     |                        |
| 125  | 04/28/15 | Title   | Fletcher Jones Porsche of Fremont  | Fremont, CA  |                       |             |                     |                        |
| 4,103                                      | 11/08/15 | Perform annual/10,000-mile scheduled maintenance service  | Fletcher Jones Porsche of Fremont  | Fremont, CA  |                       |             |                     |                        |
|  |          | Drain and refill oil; replace filter (Mobil 0-W40 Synthetic)<br>Voluntary Service Action  |  |  |                       |             |                     |                        |
|  | 12/11/15 | Perform Campaign WF86 - Update DME/instrument panel   | Porsche Cars North America   |  |                       |             |                     |                        |
|  | 01/21/16 | Pre-Delivery Inspection   | Carlsen Porsche (Redwood City)   | Redwood City, CA   |                       |             |                     |                        |
| 4,245                                      | 02/26/16 | Certified as Porsche Approved (Certified Pre-Owned Vehicle)   | Carlsen Porsche (Redwood City)   | Redwood City, CA   |                       |             |                     |                        |
| 4,298                                      | 04/30/16 | Title   | Carlsen Porsche (Redwood City)   | Redwood City, CA   |                       |             |                     |                        |
| 4,305                                      | 05/06/16 | Install Porsche LED clear side marker lights  | Carlsen Porsche (Redwood City)   | Redwood City, CA   |                       |             |                     |                        |
|  | 00/00/10 | Disable door lock confirmation chirp (alarm horn) Install hardwired Valentine 1 radar/laser detector with:                          | Owner  | Bishop, GA   |                       |             |                     |                        |
|  | 06/08/16 | - Concealed Remote Display  | Owner  | Bishop, GA   |                       |             |                     |                        |
|  |          | - V1 Connection Bluetooth Dongle  |  |  |                       |             |                     |                        |
|  |          | - Brown-Out Booster   |  |  | \$87.13               |             | \$87.13             |                        |
| 4,599                                      | 06/16/16 | Install Huper-Optik Nano-Ceramic Window Tint (C70, 71% VLT, 10%   | TintSmith  | Lawrenceville, GA  |                       |             |                     |                        |
| 4,898                                      | 07/26/16 | VLR, 48% TSER, 88% IRR)   | Owner  | Bishop, GA   | \$250.00<br>\$76.00   | \$335.00    | \$250.00<br>\$76.00 |                        |
| 4,090                                      | 07/20/10 | Install T-Design Universal Phone Mount<br>Perform annual/20,000-mile Intermediate scheduled maintenance                             | Owner  | DISTIOP, GA  | \$70.00               |             | \$76.00             |                        |
|  | 09/19/16 | service   | Porsche Atlanta Perimeter  | Atlanta, GA  |                       |             |                     |                        |
|  |          | Drain and refill oil (Mobil 1 0W-40 Synthetic); replace filter & drain plug   |  |  |                       |             |                     |                        |
| 5,764                                      |          | Replace windshield wiper blades   |  |  |                       |             |                     |                        |
|  |          | Replace cabin pollen air filter   |  |  |                       |             |                     |                        |
|  |          | Perform Campaign WF86 - DME Update  |  |  |                       |             |                     |                        |
|  |          | Replace front trunk carpet  |  |  | \$894.17              | \$894.17    |                     |                        |
| 9,468                                      | 08/24/17 | Remove "P O R S C H E" and "Boxster GTS" emblems from trunk<br>Install new "P O R S C H E" and "Boxster GTS" emblems on rear bumper | Owner  | Bishop, GA   | \$192.15              |             | \$192.15            |                        |
|  |          | Remove rear spoiler   |  |  | \$192.15              |             | \$192.15            |                        |
| 9,964                                      | 09/02/17 | Install Spyder ducktail replica spoiler   | Owner  | Bishop, GA   | \$575.00              |             | \$575.00            |                        |
|  |          | Perform annual/30,000-mile scheduled maintenance service  |  |  |                       |             |                     |                        |
| 11,045                                     | 11/06/17 | Drain and refill oil (Mobil 1 0W-40 Synthetic); replace filter & drain plug   | Porsche Atlanta Perimeter  | Atlanta, GA  |                       |             |                     |                        |
|  |          | Flush and refill brake fluid  |  |  | \$473.26              | \$473.26    |                     |                        |
|  | 01/29/18 | Mount & balance Michelin Pilot Sport 4S 235/35 & 265/35 ZR20 N0 tires<br>Perform alignment  |  |  |                       |             |                     |                        |
|  |          | - Front Camber: -0°50'/-0°52'   | Porsche Atlanta Perimeter  | Atlanta, GA  |                       |             |                     |                        |
|  |          | - Front Caster: 8°41'/8°35'   |  |  |                       |             |                     |                        |
|  |          | - Front Toe: 0°01'/0°01'  |  |  |                       |             |                     |                        |
| 11,783                                     |          | - Total Front Toe: 0°02'  |  |  |                       |             |                     |                        |
|  |          | - Steer Ahead: 0°00'  |  |  |                       |             |                     |                        |
|  |          | - Rear Camber: -1°53'/-1°52'<br>- Rear Toe: 0°08'/0°08'   |  |  |                       |             |                     |                        |
|  |          | - Total Rear Toe: 0°16'   |  |  |                       |             |                     |                        |
|  |          | - Thrust Angle: 0°00'   |  |  | \$1,863.12            | \$1,863.12  |                     |                        |
|  | 10/31/18 | Perform 4-year/40,000-mile scheduled maintenance service  |  |  |                       |             |                     |                        |
|  |          | Drain and refill oil (Mobil 1 0W-40 Synthetic); replace filter & drain plug   |  |  |                       |             |                     |                        |
| 15,241                                     |          | Perform BG 44k fuel additive service  | Hennessy Porsche   | Roswell, GA  |                       |             |                     |                        |
|  |          | Perform Ethanol Defender service<br>Replace spark plugs   |  |  |                       |             |                     |                        |
|  |          | Replace spark plugs<br>Replace engine air filters   |  |  |                       |             |                     |                        |
|  |          | Replace cabin pollen air filter   |  |  |                       |             |                     |                        |
|  |          | Perform Frigi-Fresh service   |  |  |                       |             |                     |                        |
|  |          | Replace windshield wiper blades   |  |  |                       |             |                     |                        |
|  |          | Diagnose deteriorating windshield seal  |  |  |                       | A4 000 50   | 1                   |                        |
| 17,703                                     | 10/09/19 | Replace windshield<br>Install Porsche Silver Sport Gas Cap  | Owner  | Bishop, GA   | \$1,308.53<br>\$89.99 | \$1,308.53  | \$89.99             |                        |
| 11,103                                     | 10/03/13 | Perform annual/50,000-mile scheduled maintenance service  | Gwilei   | Dianop, GA   | 405.99                |             | φ0 <del>9</del> .99 |                        |
| 17,925                                     | 11/04/19 | Drain and refill oil (Mobil 1 0W-40 Synthetic); replace filter & drain plug   | Hennessy Porsche   | Roswell, GA  |                       |             |                     |                        |
|  |          | Flush and refill brake fluid  |  |  | \$465.65              | \$465.65    |                     |                        |
| 20,549                                     | 11/07/20 | Install Duracell Ultra Platinum SLI48AGM H6 70AH 760CCA Battery   | Owner  | Bishop, GA   | \$208.97              | \$208.97    |                     |                        |
|  |          | Perform 6-year/60,000-mile scheduled maintenance service  |  |  |                       |             |                     |                        |
|  |          | Drain and refill oil (Mobil 1 0W-40 Synthetic); replace filter & drain plug<br>Perform Power Clean fuel additive treatment service  |  |  |                       |             |                     |                        |
|  |          | Perform Power Clean fuel additive treatment service<br>Perform Puroil ethanol fuel treatment service                                |  |  |                       |             |                     |                        |
|  |          | Replace drive v-belt  |  |  |                       |             |                     |                        |
|  |          | Replace cabin pollen air filter   |  |  |                       |             |                     |                        |
| 20,646                                     | 11/09/20 | Replace A/C micro-filters   | Hennessy Porsche   | Roswell, GA  |                       |             |                     |                        |
|  |          | Perform Frigi-Fresh service   |  |  |                       |             |                     |                        |
|  |          | Replace windshield wiper blades<br>Replace front hood struts  |  |  |                       |             |                     |                        |
|  |          | Perform Campaign WKJ3 - Replace Tank Leakage Diagnosis Module   |  |  |                       |             |                     |                        |
|  |          | Replace carbon canister air filter  |  |  |                       |             |                     |                        |
|  |          | Replace fuel tank pressure switch   |  |  | \$1,098.40            | \$1,098.40  |                     |                        |
|  |          |   |  |  |                       |             |                     |                        |
|  |          |   |  | and the second second  | AT                    |             |                     |                        |
|  |          | My ownership costs to date:   |  |  | \$7,582.37            | \$6,647.10  | \$1,270.27          | \$0.0                  |
|  |          |   |  | Months of ownership:   | 60                    | 60          | 60                  |                        |
| My average ownership costs per month to da |          |   |  |  | \$126.37              | \$110.79    | \$21.17             |                        |
|  |          |   |  |  |                       |             |                     |                        |
| _  |          |   | The section of the se | and a second life of the later of the second s | AT 500.05             | 00.047.40   | 64 070-05           |                        |
|  |          |   | Total ownership co   | osts over life of vehicle:   | \$7,582.37<br>Total   | \$6,647.10  | \$1,270.27          | \$0.0<br>Post-Warranty |